

Macintosh 8•24 GC Card: QuickDraw Printer Problem (11/94)

Revised: 11/7/94 Security: Everyone

Macintosh 8.24 GC Card: QuickDraw Printer Problem (11/94)

Article Created: 30 March 1991 Article Reviewed/Updated: 07 November 1994

TOPIC -----

I'm having problems printing from a Macintosh II with a Macintosh Display Card 8•24 GC connected to a LaserWriter SC. When acceleration on the Macintosh Display Card 8•24 GC is on, QuickDraw fill patterns aren't printing properly. I am running System 6.0.5 with LaserWriter SC driver 1.1.

If I turn off acceleration on the Macintosh Display Card 8.24 GC and restart, everything works fine. But restarting each time I want to print is not a satisfactory solution.

DISCUSSION -----

After doing some testing, we discovered that this problem happens with any of Apple's QuickDraw printers. We have told Engineering about the problem and will announce a solution when we have it.

In the mean time, we suggest that you switch off the Macintosh Display Card $8\cdot 24$ GC's acceleration before printing. You can do this using the card's Control Panel without rebooting or even quitting from an open application. We realize that this isn't a solution, but it is an adequate temporary workaround.

Article Change History: 07 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94 Apple Computer, Inc.

Tech Info Library Article Number:7252