

LaserWriter IINTX: Trouble Initializing Attached Hard Drive

Revised: 6/2/92 Security: Everyone

LaserWriter IINTX: Trouble Initializing Attached Hard Drive

Article Created: 15 July 1990 Article Last Reviewed: 2 June 1992 Article Last Updated: 2 June 1992

TOPIC -----

My LaserWriter IINTX is connected to an Apple 40SC Hard drive. My hard drive's SCSI ID is set to 5 and is properly terminated. When I attempt to to initialize the hard disk using the LaserWriter Font Utility, the initialize button is always greyed out.

DISCUSSION -----

Be sure that you have:

- \bullet Connected the drive to the 50-pin SCSI connector instead of the DB-25 port serial connector on the I/O board.
- Not connected your computer to the same SCSI bus as the printer and the hard drive.
- Let the drive become ready before turning on the LaserWriter IINTX.

If all the above are correct, you may have a bad LaserWriter IINTX controller or hard drive mechanism.

Copyright 1991, 1992 Apple Computer, Inc.

Tech Info Library Article Number:7742