



# Tech Info Library

## Macintosh Portable: Replacement Part for Weak Plastic Handle

Revised: 7/29/92  
Security: Everyone

Macintosh Portable: Replacement Part for Weak Plastic Handle

=====

Article Created: 5 April 1991  
Article Last Reviewed: 29 July 1992  
Article Last Updated:

TOPIC -----

The plastic handle (630-5071) and the display housing assembly (652-0605) on my Macintosh Portable are very weak and keep breaking. Are there any solutions to this problem?

DISCUSSION -----

Some Macintosh Portable computers manufactured before July 1990 have weak plastic handles. A replacement handle is available. Contact your authorized Apple dealer for more information.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:7836