



# Tech Info Library

## System 7: CD Technology Drive and CD Setup

Revised: 9/3/92  
Security: Everyone

System 7: CD Technology Drive and CD Setup

Article Created: 19 June 1991

### Article Change History

-----  
09/02/92 - UPDATED  
• To give contact information.

### TOPIC -----

I have a CD-ROM drive from CD Technology, Inc. After I load System 7 on my Macintosh IIfx, and run the installer on the Macintosh CD Setup disk as instructed in the Group Upgrade Guide, I cannot connect the CD-ROM drive. How can I connect the CD Technology ROM drive?

### DISCUSSION -----

The CD Technology CD-ROM drive uses the system access modules on the System 7 CD Setup disk, but not the driver. After running the installer, delete the Apple CD-ROM and Apple CD Remote from the Extensions folder. Install the CD Technology driver version 1.32 (or later) in the System Folder.

NOTE: CD Technology version 1.32 causes system errors on 68000-based systems, but works correctly on 68020- and 68030-based systems.

Contact CD Technology, Inc. for the most recent information on their product; search on CD Technology for contact information.

Copyright 1991, 1992, Apple Computer, Inc.

Tech Info Library Article Number:7862