



# Tech Info Library

## Macintosh IIsi: Upgrading from 3MB Configuration

Revised: 7/17/92  
Security: Everyone

Macintosh IIsi: Upgrading from 3MB Configuration

=====

Article Created: 13 August 1991  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

TOPIC -----

How is the Macintosh IIsi 3/40 configured so it has 3MB of RAM?

Also, do the four memory slots have to be full in order for the Macintosh IIsi to operate?

DISCUSSION -----

The Macintosh IIsi has 1MB on the logic board and four 512K SIMMs installed to give a 3MB configuration.

As in all Macintosh computers, all slots of a particular SIMM bank must be filled for the machine to work properly. In the case of the Macintosh IIsi, all four slots must be filled.

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:8687