

AppleTalk Phase 2: EtherTalk Driver on Network Product Installer

Revised: 6/2/92 Security: Everyone

AppleTalk Phase 2: EtherTalk Driver on Network Product Installer

Article Created: 4 March 1992 Article Last Reviewed: Article Last Updated:

TOPIC -----

What EtherTalk driver is recommended for a Macintosh IIci running system software version 6.0.7 on an AppleTalk Phase 2 network?

DISCUSSION -----

The latest version of the EtherTalk driver is 2.0.1, which is the version needed for an AppleTalk Phase 2 network. This driver is available on the Network Product Installer disk that comes with the version 6.0.7 system software disks.

Copyright 1992 Apple Computer, Inc.

Tech Info Library Article Number:9897