



Tech Info Library

Macintosh LC II: Software Compatibility

Revised: 3/19/92
Security: Everyone

Macintosh LC II: Software Compatibility

=====

Article Created: 23 March 1992
Article Last Reviewed:
Article Last Updated:

TOPIC -----

Are there any software compatibility problems with the Macintosh LC II?

DISCUSSION -----

Software compatibility test results show no new software compatibility problems.

Some cards need latest drivers:

- The LC Ethernet card requires a ROM revision (Service upgrade).
- The Apple IIe card requires 2.1 driver (on networks, and so on).

An expansion card compatibility list ships in the Macintosh LC II box. This list indicates the versions required to run properly on the Macintosh LC II. Since we found no new software compatibility problems, no software compatibility list will be included.

Copyright 1992, Apple Computer, Inc.

Tech Info Library Article Number:9943