



Tech Info Library

Macintosh LC II: Not Capable of Running A/UX

Revised: 3/19/92
Security: Everyone

Macintosh LC II: Not Capable of Running A/UX

=====

Article Created: 23 March 1992
Article Last Reviewed:
Article Last Updated:

TOPIC -----

Can the Macintosh LC II run A/UX 3.0?

DISCUSSION -----

No, the Macintosh LC II cannot run A/UX, which puts heavier demands on hardware resources than the Macintosh operating system does.

The Macintosh LC II is not a suitable A/UX platform for the following reasons:

- The Macintosh LC II lacks an FPU.
- It has limited RAM expansion and internal hard disk space.
- It has a 16-bit data path.

Copyright 1992, Apple Computer, Inc.

Tech Info Library Article Number:9951