

LaserWriter IIf/IIg: Add RAM to Correct Margin Problems (2/95)

The LaserWriter IIf now ships with 4MB and the LaserWriter IIg ships with 8MB of DRAM. These configurations will improve the margin problems and some memory management problems.

DISCUSSION -----

If your printer has similar problems, the memory can be upgraded to these levels to resolve the problem. See your authorized Apple service provider for the upgrade.

Article Change History:
06 Feb 1995 - Reviewed for technical accuracy.

Support Information Services

Copyright 1992-95, Apple Computer, Inc.

Tech Info Library Article Number:10002