



# Tech Info Library

## Macintosh IIvx: Not Designed to Operate Vertically (7/93)

Revised: 9/14/93  
Security: Everyone

Macintosh IIvx: Not Designed to Operate Vertically (7/93)

Article Created: 19 October 1992  
Article Reviewed/Updated: 14 September 1993

TOPIC -----

Can I operate my Macintosh IIvx in a vertical position?

DISCUSSION -----

The Macintosh IIvx (and the similar Performa 600 and Centris 650) were designed, built, and tested to perform reliably in the horizontal position. When operated in the horizontal position, these computers meet or exceed Apple Computer's regulatory compliance specifications. Using these computers in any other orientation may damage sensitive internal components and isn't recommended.

Further, when you place one of these computers on a work surface, be sure the L on the left side of the system remains unobstructed.

However, should you require a vertical position for your system, you must use an appropriate accessory stand to ensure regulatory compliance and continued reliability. An appropriate stand holds the computer safely without disrupting the air flow that keeps the computer's components cool. (The Apple CD 300i functions properly on its side.)

Article Change History:  
07/13/93 - Revised to include Performa 600.  
09/14/93 - Revised to include Centris 650.

Copyright 1992, 1993, Apple Computer, Inc.

Tech Info Library Article Number:10771