



# Tech Info Library

## Macintosh IIvx: Radius Video Card and System Crashes (7/93)

Revised: 7/16/93  
Security: Everyone

Macintosh IIvx: Radius Video Card and System Crashes (7/93)

=====  
Article Created: 21 January 1993  
Article Reviewed/Updated: 13 July 1993

TOPIC -----

Is there a problem with the Macintosh IIvx (Performa 600) and the Radius Video Card?

DISCUSSION -----

There is a known incompatibility between the installed base of Radius video cards and the Macintosh IIvx (Performa 600), which may result in system crashes.

Radius has corrected the problem and has updated all presently shipping models of their video interface cards and software. Users who desire to upgrade their video interface cards to provide IIvx compatibility may obtain a Software Upgrade Kit by contacting Radius Technical Support.

To locate a vendor's address and phone numbers, use the vendor's name as a search string.

Article Change History:  
07/13/93 - Revised to include Performa 600.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:11214