

Software Utility Update 1.0 vs. HW System Update 2.0 (8/93)

What are differences between • the Software Utility Update 1.0 Disk, and

• the Hardware System Update 2.0 Disk?

DISCUSSION -----

The Software Utility Update 1.0 introduces new Apple support utility program, MacCheck. It also includes a newer version of Disk First Aid (version 7.2) than is on the Hardware System Update 2.0 disk. The version of HD SC (version 7.2) included on the Software Utility Update 1.0 disk is identical to that on the Hardware System Update 2.0 disk.

The Hardware System Update 2.0 disk, in addition to HD SC Setup 7.2 and Disk First Aid 7.1.1, provides a set of system software enhancements that improve performance on selected Macintosh computers running System 7.1. (These enhancements are not intended for Performa computers.) The Software Utility Update 1.0 disk does not include the enhancements.

For additional information on the Hardware System Update 2.0 disk, search the Tech Info Library by the search string "Hardware System Update."

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:13028