



Tech Info Library

Kensington Turbo Mouse: Supersedes Mouse Control Panel 6/94

Revised: 6/8/94
Security: Everyone

Kensington Turbo Mouse: Supersedes Mouse Control Panel 6/94

=====

Article Created: 20 September 1993
Article Reviewed/Updated: 8 Jun 1994

TOPIC -----

My computer didn't respond to double-clicks. I opened the Mouse control panel, and the Double-click Speed buttons appeared deselected. I selected the buttons, and my computer responded to double-clicks. But when I restarted, the buttons appeared deselected again.

DISCUSSION -----

Kensington Turbo Mouse software will take precedence at startup over the settings contained in the Apple Mouse control panel. The mouse uses the values allocated in the Turbo Mouse CDEV (v3.0), or the Turbo Mouse Control application program (v4.0), and respond accordingly. As with the Mouse control panel, setting the Turbo Mouse controls to the fastest setting can be inoperable for some users-they just can't click fast enough. The range of values selected for the double click speed in the Turbo Mouse Control Panel was chosen to accommodate the 5th to 95th percentile users. This means that if you select the farthest extreme to the right some users might have a problem generating a double click. Try decreasing the speed in the control panel.

Article Change History:
8 Jun 1994 - Updated the article with information from Kensington.

Support Information Services

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:13357