



Tech Info Library

MacCheck: RAM Doubler Caused ROM Check to Fail (4/94)

Revised: 4/18/94
Security: Everyone

MacCheck: RAM Doubler Caused ROM Check to Fail (4/94)

=====

Article Created: 18 April 1994

TOPIC -----

When I run MacCheck on my Performa 550, the ROM check failed and Logic Board test failed.

DISCUSSION -----

You probably have a third party extension such as RAM Doubler that patches the ROM code. Start with Extensions off by holding down the Shift key after choosing Restart. Then run MacCheck again. It should not report a problem.

RAM Doubler patches the ROM which causes the Checksum to no longer match. This will cause the error in MacCheck.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15154