

LaserWriter Pro 810: PRO810V1 UNIX File Not Missing (5/94)

Revised: 5/2/94
Security: Everyone

LaserWriter Pro 810: PRO810V1 UNIX File Not Missing (5/94)

Article Created: 2 May 1994

TOPIC -----

I am trying to get the LaserWriter Pro 810 to boot it's IP address from my Sun using RARPD. I was installing the support software from the floppy provided and I noticed the load file described in the manual, PRO810V1, was not on the disk. I would like to request the LaserWriter Pro 810 load file so that our Sun workstations can print to our LaserWriter.

DISCUSSION -----

The load file PRO810V1 is not needed. The ROMs that are installed in the LaserWriter Pro 810 contain the only (and therefore latest) version of ROM code. The PRO810V1 file is only used to allow updates of the ROM. This is why this file is not included with the printer. The IP address can be set using RARPD without the PRO810V1 file.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15243