



Tech Info Library

Fax Viewer: Incompatible With Early GCC Print Drivers (5/94)

Revised: 5/5/94
Security: Everyone

Fax Viewer: Incompatible With Early GCC Print Drivers (5/94)

=====

Article Created: 5 May 1994

TOPIC -----

I have a Power Macintosh 6100 and a GCC PLP2 SCSI printer. I cannot print with the Fax Viewer 1.5.1 application program. I have the GCC PLP2 driver version 3.0.2.

When I print I only get blank pages. When I try the Print Preview option, it is also blank. Is there an incompatibility with the GCC PLP2 SCSI printer and the Fax Viewer application?

DISCUSSION -----

Since we printed a fax successfully on a Personal LaserWriter SC, from a Power Macintosh 6100 and Fax Viewer 1.5.1, we suspect you have encountered a third party driver incompatibility.

We learned from GCC Tech Support that the PLP2 SCSI printer driver v3.0.2 is not recommended or compatible with Power Macintosh computers. They were surprised it worked in some situations. They recommend you upgrade to v4.1.2 of the print driver.

Please contact GCC Tech Support for the upgrade details.

For your information Print Preview is a GCC feature, and in this case the preview being blank is indicative, GCC says, of an incompatibility.

To locate a vendor's address and phone numbers, use the vendor name as the search string.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Tech Info Library Article Number:15291