



Tech Info Library

Workgroup Server 8150 and 9150: PDS Needs Terminator (6/95)

Revised: 6/22/95
Security: Everyone

Workgroup Server 8150 and 9150: PDS Needs Terminator (6/95)

=====

Article Created: 6 May 1994
Article Reviewed/Updated: 22 June 1995

TOPIC -----

This article describes the need for a PDS bus terminator on the Apple Workgroup Servers (WS) 8150 and 9150.

DISCUSSION -----

The PDS terminator was intended and marketed only with the Workgroup Servers 8150 and 9150. This card is used only to terminate the bus via resistors installed on it. Although it was not intended (nor tested) in the Macintosh 7100 series computers, it should work fine in these systems. The part, PDS Terminator Board, is service part number 922-0967.

Article Change History:
22 Jun 1995 - Reviewed for technical accuracy
21 Jun 1995 - Updated for clarification.
10 Jan 1995 - Revised title and discussion slightly.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Tech Info Library Article Number:15354