



Tech Info Library

LaserWriter Pro 810: No Parallel Support (8/94)

Revised: 8/30/94
Security: Everyone

LaserWriter Pro 810: No Parallel Support (8/94)

=====

Article Created: 30 August 1994

TOPIC -----

According to information found in the 8/94 version of the Apple Facts product guide the LaserWriter Pro 810 supports simultaneous connections to LocalTalk, Ethernet, serial, and parallel interfaces. How do I obtain the parallel interface?

DISCUSSION -----

Early versions of the Apple Facts guide dated through 8/94 contain an error in the LaserWriter Pro 810 section by referring to a parallel interface on the LaserWriter Pro 810. The LaserWriter Pro 810 does NOT include a parallel port, but does include Ethernet, RS-232 serial, and LocalTalk interfaces.

Due to last minute changes in the printer product lineup a parallel printer interface card for the LaserWriter Pro 810 was inadvertently left on the service price pages. The part is listed as Apple service part number 661-0850 and is called a communications card. Although this parallel card can be installed in the LaserWriter Pro 810 in place of the Ethernet option, Apple does not provide support for it. The card will be removed from the service price pages shortly.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:16142