



Tech Info Library

MODE32 v.7.5: Incompatible With Launcher (5/95)

Revised: 5/25/95
Security: Everyone

MODE32 v.7.5: Incompatible With Launcher (5/95)

Article Created: 19 October 1994
Article Reviewed/Updated: 25 May 1995

TOPIC -----

The Launcher does not work with Connectix's Mode32 v7.5 on the following CPUs:

- Macintosh II
- Macintosh IIX
- Macintosh IICx
- Macintosh SE/30

When the Launcher is opened, the window is empty. Turning off Mode32 lets the Launcher show all of its items.

DISCUSSION -----

This problem has been resolved by the System 7.5 Update 1.0.

These articles can help you locate the software update mentioned here:

- Where To Find Apple Software Updates
Lists online services for "free" Apple software updates.
- Obtaining Apple Product Support in the USA
Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library.

Article Change History:

25 May 1995 - Added information about System 7.5 Update 1.0.
14 Feb 1995 - Updated keyword; reviewed for technical accuracy.
02 Feb 1995 - Removed invalid workaround information.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Tech Info Library Article Number:16561