



# Tech Info Library

## System 7.5: Problems with Video Mirroring (2/95)

Revised: 2/14/95  
Security: Everyone

System 7.5: Problems with Video Mirroring (2/95)

=====

Article Created: 1 November 1994  
Article Reviewed/Updated: 14 February 1995

TOPIC -----

Ever since I installed System 7.5 on my PowerBook, I have been experiencing system crashes when I try to use Video Mirroring. The crash always occurs when I select a menu item from the Label menu in the Finder.

DISCUSSION -----

This behavior seems to only occur under the following conditions:

- System Software 7.5 is installed.
- Video mirroring is enabled.
- 32-bit addressing is disabled.

It appears that the problem does not occur when 32-bit addressing is turned on. Check to see that 32-bit addressing is turned on when using the video mirroring functionality. Doing this should keep the problem from reoccurring.

Article Change History:  
14 Feb 1995 - Updated keyword; reviewed for technical accuracy.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Tech Info Library Article Number:16650