

Multiple Scan Display: High Pitched Whine at Highest Res. (4/95)

If the screen on the display is operating normally while the noise is occurring, then the problem is most likely related to a sub-harmonic of the horizontal sweep frequency--that is why the noise occurs only in one resolution.

This suggests that the flyback transformer is probably the culprit. Replacement of the main board is the best way to resolve this issue; there are no adjustments to reduce or remove the noise.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number: 17634