



# Tech Info Library

## GeoPort Adapter: Conflict with DOS Compatibility Card (3/97)

Revised: 3/12/97  
Security: Everyone

GeoPort Adapter: Conflict with DOS Compatibility Card (3/97)

=====

Article Created: 22 May 1995  
Article Reviewed/Updated: 12 March 1997

TOPIC -----

When I try connecting to the GeoPort Telecom Adapter from my Power Macintosh DOS Compatibility Card, the DOS Compatibility Card hangs. If I use my Macintosh communication applications or temporarily use an external modem with the DOS Compatibility Card, everything works properly.

DISCUSSION -----

The GeoPort has not been tested with any version of Apple Computer's DOS Compatibility products, and it is not supported in this environment.

Affected Products

-----

- DOS Compatibility Card for Power Macintosh 6100 or Performa 6100 Series.
- 7-in. and 12-in. PC Compatibility Cards for Power Macintosh Computers.
- GeoPort Telecom Adapter (includes ALL versions internal and external).

This article appeared in the Information Alley on 26 September 1996.

Article Change History:

12 Mar 1997 - Updated to reflect internal adapters also affected.  
25 Sep 1996 - Changed distribution status.  
22 May 1996 - Added PC Compatibility Card info.

Copyright 1995-97, Apple Computer, Inc.

Tech Info Library Article Number:17797