

Tech Info Library

Personal LaserWriter LS: Time Out Error (6/95)

TOPIC -----

I am using System 7.5 and a Personal LaserWriter LS printer. When I attempt to print from any application, I intermittently get an error message stating that there is a receive time out error and to check the Peripheral-8 cable.

DISCUSSION -----

This error occurs when using the LaserWriter LS driver and System 7.5. The correct driver to use with the LaserWriter LS and System 7.5 is the LaserWriter 300 driver (v. 1.2). This version of the LaserWriter 300 driver is included with System 7.5, and it is also available on the online services.

These articles can help you locate the software update mentioned here:

- "Where To Find Apple Software Updates" Lists online services for free Apple software updates.
- "Obtaining Apple Product Support in the USA" Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number: 18053