



# Tech Info Library

## LaserWriter 16/600 PS: Lantastic Spooler Issues (12/95)

Revised: 12/11/95  
Security: Everyone

LaserWriter 16/600 PS: Lantastic Spooler Issues (12/95)

=====

Article Created: 11 December 1995

TOPIC -----

I am having some difficulties with my LaserWriter 16/600 PS printer, which is connected to a MS-DOS Lantastic Server. When printing PCL (LaserJet emulation), the graphic information does not print, and the job either takes a long time to print, or does not print until a job is spooled.

DISCUSSION -----

When the Lantastic spooler gets corrupted, graphic information does not get sent to the printer. You need to contact Artisoft to get instructions on how to regenerate the spooler.

The LaserWriter 16/600 PS printer requires a CTRL-D at the end of a print job to flush the buffer and cause the job to print. The CTRL-D is not being placed at the ends of your print jobs, this is why it sometimes takes two tries to print. You can manually flush the printer but pressing the combination of CTRL-ALT-PRTSCLN keys.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:19047