



Tech Info Library

Macintosh Computers: Personal LW SC & IIsC Printing Issue (1/97)

Revised: 1/29/97
Security: Everyone

Macintosh Computers: Personal LW SC & IIsC Printing Issue (1/97)

Article Created: 4 January 1996
Article Reviewed/Updated: 29 January 1997

TOPIC -----

I have a Macintosh computer and an Apple Laserwriter IIsC. When I print to a LaserWriter IIsC (SCSI) printer from a variety of applications the fonts seem to overflow the area that is designated for the text. It looks fine on the screen, but this problem happens every time I print to this pritner.

Other printers accessed over LocalTalk or EtherTalk work fine. I have no extra SCSI devices (internal or external). I am not using any font management software like ATM or Suitcase. I am using true type fonts. Helvetica and Times are the two fonts that I use the most. What's wrong?

DISCUSSION -----

Issue

All Macintosh computers, including PowerBook computers, have a compatibility issue with Personal LaserWriter SC driver version 7.0.1 (included with System software 7.1.1 and 7.5) or earlier versions.

When printing from a Macintosh computer using System Software 7.5.2 or newer to a LaserWriter IIsC or Personal LaserWriter SC, the line layout is very poor and definitely not "what you see is what you get" (WYSIWYG).

Workaround

The only workaround is to use QuickDraw GX. The LaserWriter IISC GX printer driver is used for both models of LaserWriter SC (the Personal LaserWriter SC and the LaserWriter IIsC).

Article Change History:
29 Jan 1997 - Revised to include all Macintosh computers.

Copyright 1996-97, Apple Computer, Inc.

Tech Info Library Article Number:19162