



# Tech Info Library

## AppleVision Software Fix ReadMe (6/96)

Revised: 6/14/96  
Security: Everyone

AppleVision Software Fix ReadMe (6/96)

=====

Article Created: 14 June 1996

TOPIC -----

This article is the AppleVision Software Fix for System 7.5 Update 2.0 Read Me File.

DISCUSSION -----

This document contains important information for AppleVision customers.

Who needs to install the AppleVision Software Fix?

-----  
If you have an AppleVision Display and you have problems after installing the System 7.5 Update 2.0, you should install the AppleVision Software Fix. This software fixes such problems as:

- When you press the buttons on the front of the display, you see a message that says "No AppleVision Display is connected."
- You have a Power Macintosh 7200 and can't find the Monitors & Sound control panel in the Control Panels folder.
- The Monitors & Sound control panel does not have Geometry, Color, and Monitor Sound buttons. (Note: The Monitor Sound button appears only if you have an AV monitor.)
- You can't change the resolution of the AppleVision Display or you can't open the AppleVision Setup control panel.
- Macintosh Guide does not contain information on the AppleVision Software or Display.

How to install the AppleVision Software Fix

-----  
After you install System 7.5 Update 2.0 and AppleVision Software 1.0.x, you can install the AppleVision Software Fix. Follow these steps:

- 1) If you don't already have an AppleVision Software Fix floppy disk, then copy the AppleVision Software Fix online disk image to a floppy disk.

- 2) Insert the floppy disk in your computer and double-click the Installer icon.

What is installed?

-----  
On a 68040 or non-PCI Power Macintosh computer, the installer adds the following files to the System Folder:

- (1) Display Enabler version 2.0.2 is added to the Extensions folder.
- (2) AppleVision Guide Additions version 1.1 is added to the Extensions folder.

On a PCI-based Power Macintosh computer, the installer adds the following files to the System Folder:

- (1) Monitors & Sound version 1.1 is added to the Control Panels folder.
- (2) SystemAV version 1.1 is added to the Extensions folder.
- (3) AppleVision version 1.0.4 is added to the Extensions folder.
- (4) Monitors & Sound Guide Additions version 1.0 is added to the Extensions folder.
- (5) AV Monitors Guide Additions version 1.0 is added to the Extensions folder.
- (6) SimpleSound version 1.0 is added to the Apple Menu Items folder.

If you have a 68040 or non-PCI Power Macintosh

-----  
When you installed System 7.5 Update 2.0, if you used the Custom Install option to put the Monitors & Sound control panel on a 68040 or non-PCI Power Macintosh, the AppleVision software will not work. To use the AppleVision Software, follow these steps:

- 1) Remove the Monitors & Sound control panel from the Control Panels folder.
- 2) Remove AppleVision extension from the Extensions folder.
- 3) Restart the computer.
- 4) Install AppleVision Software version 1.0.x.
- 5) Install the AppleVision Software Fix.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:20037