



# Tech Info Library

## LaserWriter Pro 810: Common RCF Errors (7/96)

Revised: 7/11/96  
Security: Everyone

LaserWriter Pro 810: Common RCF Errors (7/96)

Article Created: 11 July 1996

TOPIC -----

This article describes the most common errors that can appear on the Remote Control Facility (RCF) when the LaserWriter Pro 810 printer is powered on.

DISCUSSION -----

The following error appears when the LaserWriter Pro 810 printer has a thinnet Ethernet connector, and is not connected to a properly terminated thinnet network:

LAN XLP FAIL Error Level = 03

Server -910- Ethernet cable possibly open at 0 ns (0 ft thin, 0 ft thick)  
Server -922- Non-fatal error detected by selftest, code = ++++2

This error does not affect other forms of networking or printing.

The following error appears when the LaserWriter Pro 810 printer has a twisted pair Ethernet connector, and is not connected to a properly terminated twisted pair network:

LAN XLP FAIL Error Level = 08  
Server -922- Non-fatal error detected by selftest, code = ++++2

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:20160