

Global Village Modems: Smeared Status Bar in PPP Sessions (9/96)

According to Global Village, version 2.5.2v2 of FreePPP resolves this issue.

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number: 20401