



Tech Info Library

ARA MultiPort Server 2.1 and Serial PCI Card Issue (9/96)

Revised: 9/18/96
Security: Everyone

ARA MultiPort Server 2.1 and Serial PCI Card Issue (9/96)

=====

Article Created: 18 September 1996

TOPIC -----

I received Apple Remote Access MultiPort (ARA MP) Server 2.1 with my Workgroup Server, but I cannot get ARA to recognize the Serial PCI card I purchased separately for the computer. Why will this not work?

DISCUSSION -----

The ARA MP Server v2.1 that ships with the Workgroup Server 7250 and 8550 works only with the built-in enabler on those computers. Only ARA MP Server v2.1.1 supports PCI cards. There is no upgrade from the bundled version (2.1) of ARA MP Server to 2.1.1. If you wish to use ARA MP Server with a PCI card, you should purchase version 2.1.1.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:20410