



Tech Info Library

Easy Install of 7.5.3 Does Not Install TokenRing Drivers (11/96)

Revised: 11/7/96
Security: Everyone

Easy Install of 7.5.3 Does Not Install TokenRing Drivers (11/96)

=====

Article Created: 7 November 1996

TOPIC -----

I cannot seem to get the System 7.5.3 Installer to "Easy install" the TokenRing drivers on my PowerBook (Duo) 280c. I am running the installer when the PowerBook is docked into a docking station which has a Token Ring card installed. It is as if the TokenRing card is not being recognized by the installer.

I tried doing a "clean install" of System 7.5.3 from the 7.5.3 CD-ROM disc, but still no TokenRing drivers were installed. Why is this happening?

DISCUSSION -----

This situation you encountered appears to be, from our testing results, an issue with the installer, not with your hardware. This situation occurs in all Macintosh models that have TokenRing cards installed, not just the PowerBook Duo in a docking station.

The "Easy Install" option of System Software 7.5.3 CD-ROM disc does not properly detect the presence of an Apple TokenRing card, hence does not install the necessary drivers. You must select "Custom Install" and then "Networking" and "TokenTalk" to get the drivers installed.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:20625