

[Home](#) - [CD Index](#) - [Feedback](#)

[Apple Spec DB](#) - [Hard Drives Matrix](#) - [Memory Guide](#) -
[Parts DB](#) - [Service Manuals](#) - [Software Troubleshooting](#)

[Service Programs Manual Index](#) - [U.S.](#) - [Canada](#)

[CompTIA Codes](#) - [Ordering Parts FAQ](#) - [Product Service](#)
[Matrix](#) - [REAs](#) - [Service Excellence](#)

Tech Info Library

TITLE

iMac: Hole in I/O Door Not For Cables

Article ID: 58055
Created: 8/28/98
Modified: 10/8/99

TOPIC

I routed all of my cables through the hole in the I/O door on my iMac, but it is hard to open because there is not enough room for my finger. Should the cables not be routed through the hole?

DISCUSSION

As pictured in step 5 of the tri-fold "Welcome to your iMac" pamphlet, the cables should be routed through the large gaps at the bottom of the I/O door. The large hole provides the only convenient means of opening the I/O door. Routing cables through the hole may also cause them to become disconnected when the I/O door is opened.

The iMac (Slot Loading) does not have a door over the I/O ports so this is not an issue.

EXTENDED Information - Apple Internal Use - Service Providers and Support Professional

Document Information

Product Area: iMac
Category: iMac Hardware
Sub Category: General Topics