



Tech Info Library

Apple IIC: Cable structure to Olympia RO

Revised: 11/7/85
Security: Everyone

Apple IIC: Cable structure to Olympia RO

=====

APPLE IIC	OLYMPIA RO
-----------	------------

2-----	3
3-----	7
4-----	2
5-----	4

NOTE: Use factory dip switch settings for printer.

Clinton Computer, MD

Tech Info Library Article Number:1448