

Macintosh XL: Unable to Double Click

Revised: 7/30/87 Security: Everyone

Macintosh XL: Unable to Double Click

Because the Macintosh XL has no battery backup for parameter memory, the Control Panel settings are lost if the system is unplugged. One symptom: the system does not respond to double clicks. It is then necessary to reset the Control Panel settings with the Control Panel desk accessory found in the Apple menu. The double click is controlled by the buttons next to the picture of the mouse in the lower left corner of the Control Panel.

Tech Info Library Article Number:1621