

## Apple IIGS: VGC and ROM Upgrade Notes

Revised: 7/26/89 Security: Everyone

Apple IIGS: VGC and ROM Upgrade Notes

-----

Article Created: 20 August 1987 Article Last Reviewed: 17 July 1992

Article Last Updated:

The serial number cutoffs given in the August Service and Support Notice to determine which Apple IIGS systems need the VGC and ROM upgrade are incorrect.

Use the first three digits of the serial number on the bottom of the Apple IIGS to determine which of the two upgrades a computer needs:

- when the first three digits of the computer's serial number are 704 or lower, both the new VGC and the ROM upgrade are required.
- when the first three digits of the computer's serial number are 705 through 724 (inclusive), only the new ROM is required.
- when the first three digits of the computer's serial number are 725 or higher, neither of the upgrades is required.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:2342