



Tech Info Library

Macintosh II: Always Keep It Horizontal

Revised: 7/14/92
Security: Everyone

Macintosh II: Always Keep It Horizontal

=====

Article Created: 3 February 1988
Article Last Reviewed: 30 June 1992
Article Last Updated:

TOPIC -----

Can I use my Macintosh II in a vertical orientation?

DISCUSSION -----

A Macintosh II, or Macintosh IIX and Macintosh IIfx, should always be kept horizontal.

Standing it on end

- voids the warranty
- defeats the cooling design
- will eventually damage the main unit.

The above remains true even if the required 4 to 6 inches of clearance is maintained around the vents.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:2525