



Tech Info Library

Apple II Workstation Card: No Apple IIGS Support (2/97)

Revised: 2/12/97
Security: Everyone

Apple II Workstation Card: No Apple IIGS Support (2/97)

=====

Apple II Workstation Card: Apple IIGS Support (2/97)

Article Created: 03 August 1989
Article Reviewed/Updated: 12 February 1997

TOPIC -----

This article discusses the Apple II Workstation card and Apple IIGS support.

DISCUSSION -----

The Apple II Workstation Cards is not supported in the Apple IIGS because of the following reasons.

* When the Apple II Workstation Card is installed, only ProDOS 8 applications can run. The Workstation Card tells the server that it is an Apple IIe. Therefore, it will not work in a ProDOS 16 network environment. Typically, this means only the first 64K of memory will be used.

* The Workstation Card is not fully tested in this configuration and it is not supported by Apple.

Article Change History:
12 Feb 1997 - Reviewed for technical accuracy, revised formatting.

Copyright 1989-97, Apple Computer, Inc.

Tech Info Library Article Number:4000