

## AppleCD SC: Problem Mounting with Scanner and Macintosh IIx

Revised: 8/21/89 Security: Everyone

AppleCD SC: Problem Mounting with Scanner and Macintosh IIx

\_\_\_\_\_\_

This article last reviewed: 22 June 1989

TOPIC -----

When I had an Apple Scanner and AppleCD SC attached to a Macintosh IIx, I couldn't get the AppleCD SC to mount a disk. Instead, I'd get the standard DIBadmount dialog box, which would ask me if I wanted to initialize the disk. I'm certain the AppleCD SC and Apple Scanner were properly cabled and all software correctly installed.

DISCUSSION -----

Apple Tech Comm has seen this problem, but cannot reliably reproduce it. In the past, we have been able to eliminate the problem by installing version 1.0 of the CD-ROM drivers, followed by reinstalling version 2.0 of the drivers. Recently, however, we learned that the problem could be caused by a faulty terminator. Replacing the terminator usually solves the problem.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:4128