

Apple Two-Page Monitor: Correction to Slot Info in Manual

Revised: Security:	10/22/90 Everyone
Apple Two-Page	Monitor: Correction to Slot Info in Manual
===========	
This article la	ast reviewed: 12 July 1989
TOPIC	
	ion for the Apple Two-Page Monochrome Monitor states that the be the card closest to the power supply. Is this necessary,
DISCUSSION	
	the Apple Two-Page Monochrome Monitor is incorrect. You can put in any slot. This statement will be removed from the manual in

Copyright 1989 Apple Computer, Inc.

its next revision.

Tech Info Library Article Number:4139