



Tech Info Library

LaserWriter: Blank Test Page May Be From Downloaded PostScript

Revised: 8/8/91
Security: Everyone

LaserWriter: Blank Test Page May Be From Downloaded PostScript

=====

Article Created: 12 April 1991
Article Last Reviewed:
Article Last Updated:

TOPIC -----

My LaserWriter IINTX works normally, except that the test print page is blank. The unit prints all other pages with no problem. What does this mean?

DISCUSSION -----

If you have downloaded any PostScript programs to the printer, the test page may have been blanked out unintentionally. If this is the case, the fact that the sheet is blank does not point to any hardware failure.

If you have not downloaded any PostScript programs the blank test page could be a sign of future I/O problems.

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:7528