



Tech Info Library

Macintosh: Error 51 Unserviceable Slot Interrupt

Revised: 9/9/91
Security: Everyone

Macintosh: Error 51 "Unserviceable Slot Interrupt"

=====

Article Created: 4 June 1991
Article Last Reviewed: 21 July 1992
Article Last Updated:

TOPIC -----

What is error ID=51? I get a system bomb when I try to log on to my Ethernet network.

DISCUSSION -----

That error is: "Unserviceable slot interrupt."

In general, this type of error is caused by a corrupt operating system, Ethernet driver, or a software incompatibility between any of these and INITs or CDEVs. Try trashing and re-installing the operating system and Ethernet drivers. If that fails to solve the problem, try removing all unnecessary third-party INITs and CDEVs. If the system works at this point, re-install them one at a time and restart each time to find the culprit.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:8101