

## AccessPC v1.1: Requires AppleCD SC Driver v3.1

Revised: 9/10/91 Security: Everyone

AccessPC v1.1: Requires AppleCD SC Driver v3.1

\_\_\_\_\_

Article Created: 13 May 1991 Article Last Reviewed: 31 May 1991 Article Last Updated:

TOPIC -----

When AccessPC v1.1 is installed, I cannot mount a CD that has been formatted using the ISO 9660 File Access method. Before the CD driver can determine that a different file access method is required to mount the CD, AccessPC takes over and reports the volume an uninitialized.

I am using System 7.0 with the latest CD drivers (Apple CD-ROM extension v3.0).

DISCUSSION -----

We were able to duplicate the problem you describe. The solution is to use the latest version of the AppleCD SC drivers (version 3.1).

Copyright 1991 Apple Computer, Inc.

Tech Info Library Article Number:8293