



Tech Info Library

A/UX: Does Not Recognize ADB Port as a tty Port

Revised: 11/11/92
Security: Everyone

A/UX: Does Not Recognize ADB Port as a tty Port

=====

Article Created: 11 September 1991

Article Change History

08/31/92 - REVIEWED

- For technical accuracy.

TOPIC -----

Does A/UX recognize the ADB (Apple Desktop Bus) port as a tty port?

DISCUSSION -----

No, it doesn't.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:9203