



# Tech Info Library

## Ethernet NB Card: LW Bridge 1.0 Is Not Compatible (6/95)

Revised: 6/2/95  
Security: Everyone

Ethernet NB Card: LW Bridge 1.0 Is Not Compatible (6/95)

Article Created: 1 December 1992  
Article Reviewed/Updated: 2 June 1995

TOPIC -----

Is the LaserWriter Bridge 1.0 Utility compatible with the Apple Ethernet NB Card?

DISCUSSION -----

No. We called Sonic Systems Technical Support. They told us their LaserWriter Bridge 1.0 Utility software product does not work with the Apple Ethernet NB Card (M0417LL/A). They said the LaserWriter Bridge 1.0 Utility does work properly with the old Apple EtherTalk NB Card (M0410LL/A).

They also said they have no plans to upgrade their product to work with the Apple Ethernet NB Card (M0417LL/A). For more information, please contact Sonic Systems, Inc. The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

The LaserWriter Bridge 2.0 is compatible, and you can obtain it free. It is included on the Network Software Installer (NSI) 1.5 disk.

The LocalTalk Bridge is also fully compatible, and is sold as a separate product (M3246Z/A).

These articles can help you locate the NSI 1.5 software mentioned here:

- "Where To Find Apple Software Updates" -- Lists online services for free Apple software updates.
- "Obtaining Apple Product Support in the USA" -- Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

Part numbers mentioned in this article are accurate as of this writing. Before

ordering, verify that they are still correct as they are subject to change.

Article Change History:

02 Jun 1995 - Added LaserWriter Bridge 2.0 and LocalTalk Bridge.

17 Oct 1994 - Changed LaserBridge to LaserWriter Bridge Utility.

Support Information Services

Copyright 1992-95, Apple Computer, Inc.

Tech Info Library Article Number:10745