

Macintosh IIvx: IIci Cache Card, Accelerator Slot Incompatible

Revised:	10/13/92
Security:	Everyone
Macintosh IIvx:	IIci Cache Card, Accelerator Slot Incompatible
=========	.======================================
Article Created	d: October 19, 1992
TOPIC	
Can I use the I	Ici Cache Card in the new Accelerator slot?
DISCUSSION	

No. The Macintosh IIci Cache Card is incompatible with the new accelerator slot. The accelerator slot does not accommodate cache-only cards.

Macintosh IIvx has its cache architecture on the logic board, which means the accelerator slot is left open for a third-party accelerator card.

Accelerator cards such as $50~\mathrm{MHz}$ $68030\mathrm{s}$ or cards based on $68040\mathrm{s}$ are meant for this slot.

Copyright 1992, Apple Computer, Inc.

Tech Info Library Article Number:10773