

## Tech Info Library

## Macintosh Duo Dock: How to Replace Missing or Lost Keys (1/93)

If the key is missing from the box of a new Duo Dock, customers should contact the Apple Customer Assistance Center (800-776-2333). The entire Lock Plug (Part Number 922-0108) on the Duo Dock must be replaced. The lock will be sent to the customer's authorized Apple service provider, who can install it.

Lost Key

If the key has been lost, the customer has three options to replace the keys:

• Contact the lock vendor to order a replacement set of keys.

Fort Lock Corporation 3000 N. River Road River Grove, IL 60171 708-456-1100

- Have a locksmith make a replacement set of keys.
- Have an authorized Apple service provider replace the Lock Plug (see part number above).

In all cases involving lost keys, the charges for replacement will need to be paid by the customer.

Support Information Services

 $.. TIL 11218-Macintosh\_Duo\_Dock-How\_to\_Replace\_Missing\_or\_Lost\_Keys\_1-93.pdf$ 

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:11218