



# Tech Info Library

## Macintosh 630 family: Adding an Internal CD-ROM Drive (8/94)

Revised: 8/5/94  
Security: Everyone

Macintosh 630 family: Adding an Internal CD-ROM Drive (8/94)

=====

Article Created: 05 August 1994

TOPIC -----

I ordered a Macintosh 630 family computer without an internal CD-ROM drive and now want to add one. What is the part number for the drive?

DISCUSSION -----

There are two options for adding an internal CD-ROM drive to a 630 family machine.

- Order the LC 550/575 kit, part number B1551LL/A, and don't use the faceplate for the 550/575. Inside the cover of the 630, the door over the CD can be popped out with two squeeze clips.
- A specific upgrade for the 630 family will be available in the near future. Waiting for that kit is the other option.

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15995