



Tech Info Library

Macintosh 512K/512Ke: Cable Compatibility (7/95)

Revised: 7/6/95
Security: Everyone

Macintosh 512K/512Ke: Cable Compatibility (7/95)

Article Created: 27 September 1994
Article Reviewed/Updated: 06 July 1995

TOPIC -----

This article provides cable compatibility information for Apple computer systems and a variety of Apple peripherals.

The left column lists the peripherals, the right column lists the cable required to connect one of the following computers to it; Macintosh 512K and the 512Ke.

Part numbers which begin with a letter are the finished goods part number, the seven digit numbers are the service part numbers.

DISCUSSION -----

Peripheral -----	Cable part number -----
AppleFax Modem	N/A
Apple Personal Modem Apple Data Modem 2400	M0196/590-0551
Apple Modem 300 Apple Modem 1200	M0170/590-0197
Apple ImageWriter II or II/L Apple ImageWriter LQ	M0196/590-0551 (smoke), LocalTalk optional
Apple ImageWriter Printer Apple ImageWriter 15"	590-0169

LaserWriter, Plus, IInt, IIntx, IIIf, IIg	LocalTalk
LaserWriter Pro 600/630/810	
Personal LaserWriter NT, NTR	

Personal LaserWriter LS	N/A
StyleWriter & StyleWriter II	
Color StyleWriter/Color StyleWriter Pro	

Apple LaserWriter IIsc	N/A
Personal LaserWriter SC	
AppleCD SC	
Apple Hard Disk 20/40/80	
Apple Tape Backup 40SC	
Apple Scanner	
Apple Color OneScanner	
Apple Color Printer	

Article Change History:
06 Jul 1995 - Updated Cable information for ImageWriter I

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:16379