



Tech Info Library

DOS Compatibility Card: Do Not Lock Drive Container (2/95)

Revised: 5/24/95
Security: Everyone

DOS Compatibility Card: Do Not Lock Drive Container (2/95)

=====

Article Created: 11 January 1995
Article Reviewed/Updated: 22 February 1995

TOPIC -----

This article describes an error in the Readme file from the DOS Compatibility Card for the Power Macintosh.

DISCUSSION -----

On Page 6 of the Readme file, it is recommended that you lock the Drive File.

Do not lock the Drive File.

If you lock the Drive File using Get Info, the PC does not startup and several error messages appear.

Article Chagne History:
22 Feb 1995 - Added keyword; made minor updates.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:16996