

System 7.5.3: incompatible with some SuperMac NuBus cards (4/96)

Revised: Security:	
System 7.5.3: i	incompatible with some SuperMac NuBus cards (4/96)
==========	
Article Created	d: 8 April 1996
TOPIC	
	a 950 with a SuperMac NuBus video card, and ever since I updated Update 2.0 (System 7.5.3), I can no longer startup in 32-bit mode.
DISCUSSION	

There seems to be some incompatibilities in some of the older SuperMac NuBus cards and System 7.5.3. Contact Radius, which owns SuperMac, for information on workarounds and solutions.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19582