



Tech Info Library

QuickTake 200: PowerBook Connection Issues (4/97)

Revised: 4/30/97
Security: Everyone

QuickTake 200: PowerBook Connection Issues (4/97)

Article Created: 30 Apr 1997

TOPIC -----

This article dicusses issues with connecting a QuickTake 200 to different PowerBook models.

DISCUSSION -----

QuickTake 200 customers may encounter connection issues with their QuickTake camera and different PowerBook models. Below are areas to check when connecting a QuickTake camera to a PowerBook:

PowerBook 3400 w/internal modem

- Open the Modem Control Panel
- Set port to "Modem/Printer Port". DO NOT USE "Internal Modem".
- Save modem settings
- Close Modem Control Panel
- Select Chooser from the Apple Menu
- Select "Inactive for AppleTalk"
- Reboot machine (if you close internal modem from its "Close" menu item, you don't need to restart machine)

Other PowerBooks w/internal modem

- Select the PowerBook Control Panel
- Set to "Normal" mode
- Close the window
- Select Chooser from the Apple Menu
- Select "Inactive" for AppleTalk

Copyright 1997, Apple Computer, Inc.

Tech Info Library Article Number:21225